



Path: I:\2191357 Carrboro SWCS\2019 Deliverable\Working\GIS\SWCS and Curb Ramp Rating Map.mxd



TOWN OF CARRBORO

2019 Sidewalk and Curb Ramp Condition Survey



0 500 1,000 Feet
1 inch = 500 feet

Legend

- Town Limits
- Street Centerline
- Parcel Boundary

Curb Ramp Rating

- Ramp Condition**
- Poor
 - Fair
 - Fair, No Detectable Warning Strip
 - Good
 - Good, Detectable Warning Strip Needs to be Replaced
 - Good, No Detectable Warning Strip
 - Good, Other Potential Compliance Issues

Sidewalk Condition Rating

- 0 - 25 Very Poor
- 26 - 50 Poor
- 51 - 75 Fair
- 76 - 100 Good

Data Sources:
Town of Carrboro and LaBella Associates

LaBella Project No: 2191050
Date: July 2019

SCR RESULTS CURB RAMP & SIDEWALK

Figure 1